

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

S-E-C-R-E-T

50X1-HUM

COUNTRY USSR (Saratov Oblast)

REPORT

SUBJECT Airframe Plant No. 292
in Saratov

DATE DISTR. 8 January 1959

NO. PAGES 1

REFERENCES

DATE OF
INFO.PLACE &
DATE ACQ.50X1-HUM
50X1-HUM

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

A report on the Airframe Plant No. 292 in Saratov

organizational charts of the plant itself and of Shop No. 32 and the Military Representative Section at the plant;

The report contains

50X1-HUM

S-E-C-R-E-T

50X1-HUM

STATE	X	ARMY	X	NAVY	X	AIR	#	5	FBI	AEC						
(Note: Washington distribution indicated by "X"; Field distribution by "#".)																

INFORMATION REPORT INFORMATION REPORT

S-R-C-R-R-T

50X1-HUM

-2-

Plant 292 Organization and personalities

1. Airframe Plant No. 292, Jaratov, was subordinate to the Ministry of Aviation Industry (MAP), which in turn was responsible to the Council of Ministers. Between the Ministry of Aviation Industry and the Plant Director was an intermediate echelon, the Directorate for Aircraft Procurement. This was a purely military organization and had nothing to do with the actual production or supervision of the plant. All direct supervisory control of the plant stemmed from MAP, which acted upon directives received from the Council of Ministers. (Refer to page 11, Organizational Chart of Plant 292.)

[redacted]
Dementiyev (fma), who was the Minister of Aviation Industry.

2. Under the immediate control of the plant director, there were four main plant supervisory and administrative divisions and functions, e.g., engineering, personnel, welfare, and security. The latter three had no direct functions in connection with the production aspect of the plant. All this was the direct responsibility of the Chief Plant Engineer and all the shop chiefs were directly responsible to him. (Refer to page 12, Organizational Chart of Shop No. 32.)
3. In addition to these four main divisions of which the plant director had complete direct control, there were three other divisions indirectly subordinate to the plant director and directly responsible to higher echelons of command. (Refer to page 11.) These divisions were the First Section (Pervyy Oddel) directly subordinate to the MAP, the Technical Control Section (OKK - Oddel Tekhnicheskogo Kontroliya) directly subordinate to MAP, and the Military (SAV) Representatives Section subordinate to MAP through the intermediate echelon of the procurement offices.
4. The functions of the First Section were to monitor and control all the secret documents within the plant regardless of their nature, i.e., production or administrative. This section was also responsible for perfecting the personnel security checks and maintaining the files. This section was headed by Antonov (fma).
5. The plant OKK section was headed by Gorchkov (fma) and all the technical controllers (inspectors) throughout the plant were responsible to him through the chief inspector in each shop. At shop level, the inspector's section was referred to as Itak (Byuro Tekhnovogo Kontroliya - Shop Control Office). Each shop within the plant had a chief inspector, and his assistant was called the senior master inspector (starshiy kontrolnyy master). Then each section in a shop was assigned a chief inspector and each brigade in a section had one inspector.
6. In addition to the regular shop inspector described above, the plant OKK had an unknown number of military pilots assigned to it to perform the plant flight tests of the aircraft. Although they were military (SAV) pilots, they functioned for the plant and were not responsible to the Chief Military (SAV) Representative.

S-R-C-R-R-T

50X1-HUM

S-E-C-R-E-T

50X1-HUM

50X1-HUM

-3-

7. The Military Representative Section assigned to the plant was headed by Col. Kuzmin (fnu). (Refer to page 13, Organization of the Plant Military Representatives.) This section consisted of SAF officers who were assigned to various shops as military inspectors. In this respect, even though not assigned to a shop, they had the right to inspect the work performed therein and they were the final approving authority. This section also had an unknown number of military (SAF) pilots who performed the final acceptance flight tests.

50X1-HUM

Personnel

9. Afanasyev (fnu). He was the senior maintenance repair mechanic in Shop No. 32. 50X1-HUM

10. Agranovich (fnu). He was the chief of Shop No. 4.

11. Antonov, Valentin Anisimovich. He was the first assistant to the chief of Shop No. 32. 50X1-HUM

12. Antonov (fnu). He was the chief of the First Section and not related to Valentin Antonov.

13. Antyukhov (fnu). He was chief of the plant accident prevention section and worked in the training section. He was an aeronautical engineer. 50X1-HUM

14. Belokobylskiy (fnu). He was the chief of the Cost Accounting Department and worked for Suklov (fnu), the chief of the finance office. 50X1-HUM

50X1-HUM

S-E-C-R-E-T
NOFORN/CONTINUED CONTROL

S-E-C-R-E-T

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

15. Korba (fnu). [redacted] he was the Chief of the plant Maintenance and Repair Section.

16. Bondarsenko (fnu). He was the Chief of Shop No. 19.

17.

18. Chokulayev, Konstantin Pavlovich. He was the Chief [redacted] Shop No. 5. 50X1-HUM

19. Chernov (fnu). [redacted] he was chief of the First Section of Shop No. 50.

20. Chishov (fnu). He was a Senior Lieutenant in the SAF, a military inspector in Shop No. 5, and assistant to Chokulayev.

50X1-HUM

21. Derentiyov (fnu). [redacted] he was the Chief of [redacted].

22. Donisov (fnu). [redacted] he was the secretary of the CP Committee.

23. Dubovikov, Boris Aleksandrovich. He was the plant director from December 1955 to May or June 1957.

S-E-C-R-E-T

50X1-HUM

50X1-HUM
50X1-HUM

S-E-C-R-E-T

-5-

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

in the USSR that he was replaced by Dorisov.

24. Enelin, Vasily Nikolayevich. He was the Chief Inspector of Shop No. 32.

25. Entin (fnu). He was the Chief of Shop No. 122.

26. Feodorova (fnu). She was the chief bookkeeper in Shop No. 32.

27. Gorbunov (fnu).

Gorbunov was the assistant to the chief of Shop No. 5. Prior to that, from 1951 to 1953 or 1954, he was the temporary chief of the plant OTK during the absence of Zolotarev (see to below).

28. Gorodkov (fnu). He became the chief of the plant OTK in the spring of 1957.

29. Gorovenko (fnu). She was the Chief of Welfare.

30. Kollinin (fnu). He was the assistant to the chief of Shop No. 1.

S-E-C-R-E-T

50X1-HUM

S-E-C-R-E-T

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

31. Khucheturov (fnu). [redacted] chief of the plant office supplies section.

32. Kitzunov (fnu). He was a major in the SAF and the chief military representative in Shop No. 20.

33. Klimov, Lev Sergeyevich. He was the second assistant to the chief Shop No. 32.

50X1-HUM

34. Kolobanov (fnu). He was the chief of the 12th Efficiency Report Section.

50X1-HUM

35. Kopyov (fnu). He was the chief of Shop No. 6.

36. Krasnigutsky (fnu). He was a major in the SAF and one of the test pilots assigned to the plant OTK.

50X1-HUM

37. Kuzmin (fnu). He was a colonel in the SAF and the senior military representative at the plant.

50X1-HUM

38. Litinskiy, Mikhail Andrianovich. He was the chief of the Technical Section for Shop No. 122.

S-E-C-R-E-T

50X1-HUM

50X1-HUM

50X1-HUM

S-E-C-R-E-T

-7-

50X1-HUM

50X1-HUM

50X1-HUM

39. Lobaninovskiy (fmu). He was the first assistant to the chief of the plant OTK after Gorkhov assumed these duties. 50X1-HUM

40. Matyushevskiy (fmu). He was the manager of the plant club house.

41. Mirov (fmu). He was the chief technician of the plant.

42. Mironchichenko, Nikolay Yakovlevich. He was the chief plant engineer and prior to assuming this position in 1939 or 1940, he had been an aeronautical professor at the Industrial University in Kharkov.

43. Morozov, Konstantin Grigoriyevich. He was the chief of the Design Office (SKO - Seryno-Konstruktorakoye Otdeleniye) and the representative of the Yakovlev Design Office at the plant. 50X1-HUM

44. Morozov (fmu). He was the second assistant to the chief of the plant office (Gorkhov). 50X1-HUM

45.

46. Palchikov (fmu). He was the chief of personnel.

47. Pavlov (fmu). He was the chief of Plant Production.

S-E-C-R-E-T

50X1-HUM

S-E-C-R-E-T

-8-

50X1-HU 50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

48. Hlonkevich, Fredrik Georgiyovich. He was the chief of Shop No. 32.

49. Polyakov (fnu). He was the assistant to the chief of Shop No. 20.

50X1-HUM

50. Potayuk (fnu). He was the foreman of the electric wire section in Shop No. 5.

50X1-HUM

51. Rubinevich (fnu). He was the senior technologist of Shop No. 4.

52. Sergeev (fnu). He was the chief of the second section of Shop No. 30 and in charge of combine production.

53. Shnayder (fnu). At one time, presumably before 1948, he was the chief of the plant OTK.

50X1-HUM

54. Sineonov (fnu). He was the president of the Profsovet at the plant.

55. Sorokin (fnu). He was the chief of Shop No. 3.

S-E-C-R-E-T

50X1-HUM

50X1-HUM

S-E-C-R-E-T

-9-

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

56. Spirin, Viktor (patronymic unknown). He was the chief of the plant in Shop No. 4.

57. Stepanitsenko (fnu). He was a major in the JAF and chief military representative in Shop No. 5.

58. Sukhov (fnu). [redacted] that he was the chief of the finance office.

59. Temerkuryan (fnu). He was the chief of the military directorate of fighter aircraft procurement for Saratovskaya oblast.

60. Titov (fnu). He was the director of production of civilian commodities at the plant and was directly responsible to Vasil'yev, the chief of plant supply.

61. Tupitsin (fnu). He was the chief of training at the plant.

62. Vasil'yev (fnu). He was the chief of plant supply.

63. Vostokov (fnu). [redacted] chief of Shop No. 3.

S-E-C-R-E-T

50X1-HUM

50X1-HUM

~~S-E-C-R-E-T~~

-10-

50X1-HUM

50X1-HUM

50X1-HUM

4. Zolym (nu). He was chief of the plant.

~~S-E-C-R-E-T~~

50X1-HUM


S-E-C-R-E-T

50X1-HUM

-11-

50X1-HUM

Organizational Chart of Plant 292



S-E-C-R-E-T

50X1-HUM


S-E-C-R-E-T

-12-

50X1-HUM

50X1-HUM

Organizational Chart of Shop No. 32 at
Airframe Plant 292



S-E-C-R-E-T

50X1-HUM


S-E-C-R-E-T

-13-

50X1-HUM

50X1-HUM

Organizational Structure
of the office of
Plant Military Representatives



S-E-C-R-E-T

50X1-HUM